

**ENSR**

*Not FYI - on file*

January 12, 1993

**ENSR Operations**

1700 Gateway Boulevard S.E.  
Canton, Ohio 44707  
216-452-0837

New York Institute Of Technology  
268 Wheatly Road  
Old Westbury L I, NY 11568

ATTENTION: Mr William Schiraldi

SUBJECT: Reclassification Sample Results  
ENSR Operations Job No. 0676

Dear Mr Schiraldi:

Based on the fluid samples received, the laboratory  
results for your electrical equipment serviced by ENSR  
Operations are:

| <u>Transformer<br/>Serial Number</u> | <u>Original<br/>Fluid Type</u> | <u>Reclass<br/>Date</u> | <u>Reclass<br/>PPM/PCB</u> | <u>Certificate<br/>Number</u> |
|--------------------------------------|--------------------------------|-------------------------|----------------------------|-------------------------------|
| F963493                              | Ask                            | 11/06/92                | 41.0                       | 25589                         |
| F963494                              | Ask                            | 11/06/92                | 40.0                       | 25590                         |

These units are now reclassified to NON-PCB status if, prior  
to sampling the units operated for three months or more of  
regular in-service use as defined by the applicable Federal  
PCB Regulations.

Please find enclosed the laboratory certificates listed above.  
If I can be of further service, please contact me.

Sincerely,

ENSR OPERATIONS

*C M Arnold*

Charles M Arnold

Project Manager - Reclass 50

cc: Job File  
Irene Papatoukakis

*(Handwritten signature/initials)*

Box 441 - on file

... ..  
... ..  
... ..

... ..  
... ..  
... ..

... ..  
... ..  
... ..

... ..  
... ..  
... ..

... ..  
... ..  
... ..

... ..  
... ..

... ..  
... ..

... ..  
... ..

... ..  
... ..